

## Model1881XP/UXP Software Ver11.50 Added Device (Update From Ver11.40)

### Boya

BY25Q128AS @16SO(300mil)	BY25Q128AS @8SO(200mil)	BY25Q128AS @8USON(3x4)	BY25Q128AS @8USON(4x4)
BY25Q128AS @8WSON(5x6)	BY25Q64AS @8SO(150mil)	BY25Q64AS @8SO(200mil)	BY25Q64AS @8USON(3x4)
BY25Q64AS @8USON(4x4)	BY25Q64AS @8WSON(5x6)		

### ISSI

IS25WP016C @8USON(3x4)

### XTX

XT25Q01B @8SO(150mil)	XT25Q01B @8SO(200mil)	XT25Q01B @8TSSOP	XT25Q01B @8VDFN(2x3)
XT25Q02B @8SO(150mil)	XT25Q02B @8SO(200mil)	XT25Q02B @8VDFN(2x3)	XT25Q04B @8SO(150mil)
XT25Q04B @8SO(200mil)	XT25Q04B @8TSSOP	XT25Q04B @8VDFN(2x3)	